

WAC 296-304-02011 Warning signs and labels. (1) Employee comprehension of signs and labels. You must ensure that each sign or label posted to comply with the requirements of this section is presented in a manner that can be perceived and understood by all employees.

(2) Posting of large work areas. A warning sign or label required by subsection (1) of this section need not be posted at an individual tank, compartment or work space within a work area if the entire work area has been tested and certified: "Not safe for workers," "not safe for hot work," and if the sign or label to this effect is posted conspicuously at each means of access to the work area.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, and 49.17.060. WSR 17-18-075, § 296-304-02011, filed 9/5/17, effective 10/6/17. Statutory Authority: Chapter 49.17 RCW. WSR 95-04-006, § 296-304-02011, filed 1/18/95, effective 3/10/95; Order 74-25, § 296-304-02011, filed 5/7/74.]