

**WAC 296-806-20010 Protect employees from unintentional machine operation.** (1) You must make sure foot-operated controls are located or guarded so that unintentional movement to the "ON" position is unlikely.

(2) You must make sure machines will **not** automatically restart when power is restored after a power failure, if restarting would create a hazard for employees.

**Note:** Operating controls can be protected from unintentional movement by methods such as covers on foot treadles and collars around machinery start buttons.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, 49.17.060. WSR 15-24-102, § 296-806-20010, filed 12/1/15, effective 1/5/16; WSR 04-14-028, § 296-806-20010, filed 6/29/04, effective 1/1/05.]