

**WAC 16-675-035 What condition must your weights and measures standards be in when they are submitted to the laboratory for testing or calibration?** Weights and measures standards submitted to the laboratory for tolerance testing or calibration must be in a physical condition that allows the laboratory to perform the requested service.

[Statutory Authority: Chapters 19.94 and 34.05 RCW. WSR 04-23-043, § 16-675-035, filed 11/10/04, effective 12/11/04.]