

(Effective until October 1, 2020)

WAC 296-876-60025 Ladder surfaces. You must make sure all parts and surfaces of the ladder are free of splinters, sharp edges, burrs, or projections that may be hazardous to persons using the ladder.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, 49.17.060, and chapter 49.17 RCW. WSR 14-09-095, § 296-876-60025, filed 4/22/14, effective 7/1/14. Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, 49.17.060. WSR 06-16-020, § 296-876-60025, filed 7/24/06, effective 12/1/06.]

(Effective October 1, 2020)

WAC 296-876-60025 Ladder surfaces. See the fixed ladder inspection requirements under WAC 296-876-70010 Inspection and repair.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, 49.17.060 and chapter 49.17 RCW. WSR 20-09-146, § 296-876-60025, filed 4/21/20, effective 10/1/20; WSR 14-09-095, § 296-876-60025, filed 4/22/14, effective 7/1/14. Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, 49.17.060. WSR 06-16-020, § 296-876-60025, filed 7/24/06, effective 12/1/06.]